

STANDARD CHARGE := For fault finding / repairs we charge £84 per hour or part thereof.

PRICE LIST 2024

(Indication Only)

All prices include VAT.

The below prices relate to normal working hours (8am to 5pm)

Description	Prices			Prices
Natural Gas Safety Inspection 1x Appliance	£84.00			Replace Outside Tap
Natural Gas Safety Inspection 2x Appliances	£108.00			Complete / New Outside Tap (from)
Natural Gas Safety Inspection 3 x Appliances	£132.00			Plumb-in Washing Machine (from)
Natural Gas Safety Inspection Extra Appliance	£24.00			Plumb-in Washing Dishwasher (from)
N. Gas Extra to Service Each appliances after GSI	£66.00			Renew WC Cistern - Low Level (from)
N. Gas Service to Back Boiler Unit and Fire Front	£150.00			Renew WC Pan - Low Level (from)
N. Gas Service to Combination Boiler	£95.00			Renew Wc (from)
N. Gas Service to Gas Fire	£95.00			Renew Wash Basin (from)
N. Gas Service to Wall Hung Heater	£95.00			Immersion Heater Renewal (from)
Extra to Replace the CombustionDoor Seal	£42.00			Replace Domestic Tank Complete (from)
N. Gas Service to Boiler and 1x Fire	£168.00			Heating & Domestic Tank Renewal (from)
N. Gas Service to Boiler and 2 x Fires	£234.00			Replace Heating Tank Complete (from)
Extra to Replace Thermocouple - Standard	£30.00			Replace Primatic Cylinder (from)
Extra to Replace Thermocouple - Special(upwards)	£78.00			Replace Indirect Cylinder (from)
LPG Gas Safety Inspection 1X Appliance	£120.00			Replace Direct Cylinder (from)
LPG Gas Safety Inspection extra Appliance	£30.00			Extra For Immersion Heater
LPG Extra To Service Appliance	£66.00			Renew Radiator Valve With TRV (vat at 5%)
LPG Appliance Fault Find (first hour)	£108.00			Extra For Each TRV (vat at 5%)
LPG Fault Find Extra Hour	£108.00			Extra to add Inhibitor
LPG Boiler Service	£114.00			Connect up Gas Fire With Pipe (from)
LPG Fire Service	£120.00			Remove Fire & Board up (from)
				Cooker Installation (from)
Oil Fired Appliance Fault Finding (first hour)	£102.00			Extra for Hose
Oil Fired Appliance Extra Hour	£102.00			Cooker Swap with Removal (from)
Oil Boiler Service (up to 3 hours work) inc nozzle	£162.00			Re-Washer Ball valve
Extra to replace the oil hose	£30.00			Replace Side Feed Ball valve (from)
To supply & Fit Electronic Carbon Monoxide Detector	£102.00			Replace Bottom Entry Ball Valve (from)
Boiler Swap (from) Subject to survey	£2,100.00			Re-Washer Tap
Full Central Heating Installation (from) subject to survey	£4,200.00			Plumbing & Heating Systems Report (Terraced)
To Replace Two/Three Way Valve (from)	£270.00			Plumbing & Heating Systems Report (Semi)
To Replace Time clock/Programmer (from)	£186.00			Plumbing & Heating Systems Report (Detached)
Add Inhibitor to System	£42.00			Hob Swap (fix only) (from)
Free Pump (from)	£84.00			Hob Replacement (from)
Replace Pump (assuming valves hold)	£336.00			Power Shower Pump Installation (from)

