

**STANDARD CHARGE** := For fault finding / repairs we charge £84 per hour or part thereof.

**PRICE LIST 2024**

(Indication Only)

All prices include VAT.

The below prices relate to normal working hours (8am to 5pm)

Description	Prices			Prices
Natural Gas Safety Inspection 1x Appliance	£84.00			Replace Outside Tap
Natural Gas Safety Inspection 2x Appliances	£108.00			Complete / New Outside Tap (from)
Natural Gas Safety Inspection 3 x Appliances	£132.00			Plumb-in Washing Machine (from)
Natural Gas Safety Inspection Extra Appliance	£24.00			Plumb-in Washing Dishwasher (from)
N. Gas Extra to Service Each appliances after GSI	£66.00			Renew WC Cistern - Low Level (from)
N. Gas Service to Back Boiler Unit and Fire Front	£150.00			Renew WC Pan - Low Level (from)
N. Gas Service to Combination Boiler	£95.00			Renew Wc (from)
N. Gas Service to Gas Fire	£95.00			Renew Wash Basin (from)
N. Gas Service to Wall Hung Heater	£95.00			Immersion Heater Renewal (from)
N. Gas Service to Gas Water Heater	£95.00			Replace Domestic Tank Complete (from)
N. Gas Service to Boiler and 1x Fire	£168.00			Heating & Domestic Tank Renewal (from)
N. Gas Service to Boiler and 2 x Fires	£234.00			Replace Heating Tank Complete (from)
				Replace Radiator Valve ( from)
Extra to Replace Thermocouple - Standard	£30.00			Replace Primatic Cylinder (from)
Extra to Replace Thermocouple - Special(upwards)	£78.00			Replace Indirect Cylinder (from)
LPG Gas Safety Inspection 1X Appliance	£120.00			Replace Direct Cylinder (from)
LPG Gas Safety Inspection extra Appliance	£30.00			Extra For Immersion Heater
LPG Extra To Service Appliance	£66.00			Renew Radiator Valve With TRV (vat at 5%)
LPG Appliance Fault Find (first hour)	£108.00			Extra For Each TRV (vat at 5%)
LPG Fault Find Extra Hour	£108.00			Extra to add Inhibitor
LPG Boiler Service	£114.00			Connect up Gas Fire With Pipe (from)
LPG Fire Service	£120.00			Remove Fire & Board up (from)
				Cooker Installation (from)
Oil Fired Appliance Fault Finding (first hour)	£102.00			Extra for Hose
Oil Fired Appliance Extra Hour	£102.00			Cooker Swap with Removal (from)
Oil Boiler Service (up to 3 hours work) inc nozzle	£162.00			Re-Washer Ball valve
Extra to replace the oil hose	£30.00			Replace Side Feed Ball valve (from)
To supply & Fit Electronic Carbon Monoxide Detector	£102.00			Replace Bottom Entry Ball Valve (from)
Boiler Swap (from) Subject to survey	£2,100.00			Re-Washer Tap
Full Central Heating Installation (from) subject to survey	£4,200.00			Plumbing & Heating Systems Report (Terraced)
To Replace Two/Three Way Valve (from)	£270.00			Plumbing & Heating Systems Report (Semi)
To Replace Time clock/Programmer (from)	£186.00			Plumbing & Heating Systems Report (Detached)
Add Inhibitor to System	£42.00			Hob Swap (fix only) (from)
Free Pump (from)	£84.00			Hob Replacement (from)
Replace Pump (assuming valves hold)	£336.00			Power Shower Pump Installation (from)

